

Oil Field Environmental Incident Summary

Incident: 20141030143805 **Date/Time of Notice:** 10/30/2014 14:38
Responsible Party: CONTINENTAL RESOURCES, INC.
Well Operator: CONTINENTAL RESOURCES, INC.
Well Name: LOUISVILLE 2-9H
Field Name: LAST CHANCE **Well File #:** 23532
Date Incident: 10/30/2014 **Time Incident:** 09:15 **Facility ID Number:**
County: WILLIAMS **Twp:** 153 **Rng:** 100 **Sec:** 10 **Qtr:**
Location Description:

Submitted By: Shane Knuchel **Received By:**
Contact Person: Shane Knuchel
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Cultivated **Affected Medium:** Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.2	Barrels			0.2	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 9/23/2016 **Clean Up Concluded:** 10/30/2014

Risk Evaluation:

None

Areal Extent:

Misted an area approximately 50 by 20 ft with 20 by 20 ft being off location on landowners land.

Potential Environmental Impacts:

Topsoil

Action Taken or Planned:

Standing vegetation will be mowed and bagged, then soil samples will be taken to ensure proper cleanup has occurred.

Wastes Disposal Location: To be determined.

Agencies Involved: Notified John Axtmann NDIC by phone on 10/30/2014 at 2:12 PM CT.

Updates

Date: 10/31/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Spray off location due to an unspecified cause. Followup is necessary.

Date: 11/5/2014 **Status:** Inspection

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 15:00. 45 degrees F, mostly sunny, NW wind 10-25 mph. Observed site and took photos. Spoke with the company pumper who directed me to the location of the release. It appeared that there had been two releases -- one to the southeast of the flare pit and one to the northwest of the flare pit. Vegetation to the southeast appeared to have been removed with no soil impacts. Area to the northwest still had liquid petroleum product on the vegetation and will require further followup.

Date: 11/20/2014 **Status:** Correspondence

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Received email from company contact on 11/19/14 with attached photos. Email and photos placed into folder. The vegetation in the area of concern appears (from the photos) to have been removed. On-site followup will be needed to determine if soils in the area of concern have been impacted and need to be remediated. Follow up when in the vicinity of the location.

Date: 3/10/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated March 10, 2016.